ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
DASARAHALLI	14	Bagalakunte
Street ID	**Street Name**	**Significant Landmark**
W0419	NA	Bagalagunte
Segment No.	**Total Length (m)**	
14/S-W0419/S040417	63.77	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	63.77	77.505946	13.057956	77.505654	13.058245	Balaji Scan center	park end

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Improvements to works to Storm water drain in Bagalagunte Ward No 14	2500000	2018-19
Year	**Type of Work**	**Other Work Type**
2018 - 2019	Others	CC Drain
Tender	**Work Details**	**Job No. / Work Code**
Tender		04-19-000006
Work Order No.	**Work Order Date**	**Period of Extention**
EE/DD/WO/351/18-19	12/02/2019	
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
23/02/2019	22/02/2020	No

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
Raghunandan L		2500000.00
Phone No.	**E-Mail ID**	
9900190482		

ಸಹಾಯಕ ಕಾರ್ಯಪಾಲಕ ಅಭಿಯಂತರರು
ದಾಸರಹಳ್ಳಿ ಉಪ-ವಿಭಾಗ
ಬಾಗಲಗುಂಟೆ, ಬಿಬಿಎಂಪಿ
ಬೆಂಗಳೂರು

Zone: DASARAHALLI Ward No: 14 Ward Name: Bagalakunte Street ID: W0419

Date: 10/05/2019 Time: 16:06:21 RH20190510160821 Page 1 of 1

Scanned by CamScanner